

NORTHWEST REGIONAL WASTE AUTHORITY INC.

1 4 MILES WEST OF MEADOW LAKE ON HIGHWAY 55 RR 3 1 93 (NORTH) TO
LANDFILL (EAST OF RAPID VIEW)

PO Box 262, PIERCELAND, SASK. S0M 2K0

MEADOW LAKE, GOODSOIL, DORINTOSH, LOON LAKE, PIERCELAND,
RM OF MEADOW LAKE, RM OF BEAVER RIVER AND RM OF LOON LAKE

HOURS OF OPERATION:

**MONDAY TO SATURDAY 9:00AM - 4:45PM SCALE SHUTS OFF AT 4:30 (CLOSED
ALL STAT HOLIDAYS) AND BOXING DAY**

WHAT IS PERMITTED

Unsorted Waste: Household or Commercial (all household garbage must be bagged)
Metal – including but not limited to wire, propane bottles, washers, dryers and stoves
Wood – all painted, stained or treated, plywood, OSB must go to the pit at regular tipping fees
Bagged and unbagged grass
Wood – unpainted, unstained or untreated, branches and trees (accepted at no charge)
Refrigerators, freezers, air conditioners, water coolers - \$25 – separate location on site
Mattresses or box springs -\$20 each
Clean Cement 20.00/ tonne
Tires - *must be removed from rim \$10 minimum
Grain Bags - *bags must be tightly rolled and secured. There is no charge for this service.

WHAT IS NOT PERMITTED

Oil pails or jugs
Oil
Batteries other than household
Paint
Animal carcass
Oil filters
Hydraulic hoses
Asbestos
Contaminated soil
Pesticides or herbicides (and containers)
Microwaves
T.V.'s
Stereo Equipment
Any other electronics
Large loads of recyclable materials

Methods of payment: Cash, Cheque, or Debit

Charge accounts have **30 days** from time of invoice to be repaid in full. Accounts overdue will be sent to a collection agency.

Please note:

There is no salvaging of any items allowed!

Surcharges will be applied for unsorted waste loads. Please deposit items in the appropriate areas. If requiring more information on sorting of loads please call the scale attendant at 236-4315. It is your responsibility to ensure your loads are secured and covered when hauling

Tipping Fees: \$105.00/ tonne for members of the authority. Minimum charge is \$2.00.

\$140.00/tonne for out of authority (areas that are not listed above)

Contacts:

Landfill Site Office: (306)236-4315 Fax (306) 236-4319

Site Manager: Shkopich Enviro – (306)236-5200

NRWMA Administrator: Penny Hewlett (780) 826-0497 pennyregionallandfill@gmail.com

Disposal of waste at the Northwest Regional Waste facility is subject to Ministry regulations for operating a waste disposal ground.